

HYUNDAI QUEZON AVENUE
 1144 Quezon Avenue, Quezon City
 Tel Nos. 374-3911, Fax No. 411-2721

REPAIR COST ESTIMATE

GLASSTEMP

9/17/2016

Telephone #:

Address:

MODEL: HYUNDAI I10

JOB DESCRIPTION	LABOR	MATERIALS	PARTS
REPLACE RADIATOR ASSY	2,600.00		12,400.00
UPPER RADIATOR HOSE			850.00
LOWER RADIATOR HOSE			850.00
GASKET MAKER			200.00
4-COOLANT			1,400.00
MISC		150.00	
TOTAL	2,600.00	150.00	18,700.00

Prepared by: **CHRISTIAN GILLEGO**
 Service Advisor

NOTE : THIS IS AN INITIAL ESTIMATE ONLY
OTHER DEFECTS FOUND IS CONSIDERED
ADDITIONAL

SUMMARY	
LABOR	2,600.00
MATERIALS	150.00
PARTS	15,700.00
VAT	
TOTAL REPAIR	18,450.00
ESTIMATE	
DP:	

less: 10% labor
5% parts: